



City of Columbus  
Mayor Michael B. Coleman

## *Department of Development*

Boyce Safford III, Director

### Building Services Division

757 Carolyn Avenue

Columbus, Ohio 43224-3218

(614) 645-6090

(614) 645-7840 FAX

[www.columbusonestopshop.com](http://www.columbusonestopshop.com)

**September 30, 2009**

## **Construction Industry Communication #21**

From: Keith Wagenknecht, Chief Building Official

RE: Slab-on-Grade Inspection

**Requirements:** Section 109.3.2 of the 2007 Ohio Building Code requires concrete slab and under-floor inspections be made after in-slab or under-floor reinforcing steel and building service equipment, conduit, piping accessories and other ancillary equipment items are in place, but before any concrete is placed or floor sheathing installed, including the subfloor.

**Memorandum:** *Projects that have been reviewed and receive plan approval after September 30, 2009 --* All poured in-place, slab-on-grade will require a slab inspection to be performed by a City of Columbus Building Services Division structural inspector prior to placement of concrete. This inspection will be performed to verify that the following items are installed in accordance to the approved documents:

- Slab reinforcing steel.
- Thickened areas.
- Under slab and/or perimeter insulation.
- Minimum thickness of concrete.
- Vapor retarder with joints lapped not less than six (6) inches.

For additional information, please contact Building Services Inspection Section at: **614-645-6371** or via e-mail - [osscomments@columbus.gov](mailto:osscomments@columbus.gov).